

NEW DESIGN BALL VALVE WITH HOSE UNION

We have recently redesigned the 100HU ball valve with hose union. The new design has a secondary 'O' ring seal between the seat retainer and body for extra security on the joint. The pricing remains the same but there are new part numbers which are detailed below.

| Old Part Code | New Part Code | Description |
|-----------------|-----------------|----------------------|
| 004B00100JWMABK | 004BR0100JWMABK | 1/2 100HU BALL VALVE |
| 006B00100JWMABK | 006BR0100JWMABK | 3/4 100HU BALL VALVE |
| 010B00100JWMABK | 010BR0100JWMABK | 1 100HU BALL VALVE |

For further information please see the attached data sheet.